

0645Z 11 DEC 62

SECRET

LS
DAP
TSO/017

25X1A

25X1A DIRECTOR

OSA/TCO (1-2-3-4-5-6-7-8)

TOR: 1035Z 11 DEC 62

EDD
WER
KB
RLP
RDO
PAG
SAH

PRIORITY

25X1A

IN 58859

PRITY

25X1A

25X1A

1. G-3201/9600
2. 9R/0-11-6000/UNK/9L/0-11-6000/172-10-9-6-1
3. D-19/4/75 DEGREE F/HTA-2
4. 2,02
5. GOOD/GOOD/GOOD

25X1A

6. TAKE RECEIVED 06/1617Z IN STEEL BOXES, CONDITION GOOD.

CONSIDERABLE NUMBER OF WATER SPOTS DUE TO LACK OF TRAINING ON HTA-2'S

NO TEST TAKE AVAILABLE TO OPERATE EQUIPMENT OR CHECKOUT PERSONNEL.

DUE TO TERRAIN CONDITIONS AND POOR MAPS CONSIDERABLE TROUBLE

EXPERIENCED IN LOCATING PHOTOGRAPHY. RECOMMEND THAT

BE FURNISHED TO AID IN PHOTO INTERPRETATION IN ALL

FUTURE OPERATIONS. FILM CREASE 9L, 2128. FILM DAMAGED IN

PROCESSOR, 9R 782 THROUGH 787, DUE TO BAD PRE-SPLICE. CHECK DATA

CHAMBER. CHAMBER RECORDING OVER EXPOSED. NO CAMERA MALFUNCTIONS

NOTED. DO NOT REPEAT DO NOT RECOMMEND CHANGE OF EXPOSURE OR FILTER.

SECRET

25X1A

S E C R E T

[REDACTED] (IN 58859)

PAGE TWO

25X1A

DUE TO ROTATION OF EXPERIENCED PERSONNEL REQUEST [REDACTED] BE FURNISHED
TEST TAKE TO BE USED FOR TRAINING AND MAINTAINING PROFICIENCY OF
PROCESSING PERSONNEL AND EQUIPMENT. [REDACTED]

25X1A

25X1A ARRIVED [REDACTED] DURING EARLY PART OF [REDACTED] PROCESSING PHASE.

25X1A

SITSUM TRANSMITTED 2230 HOURS, 7 DEC 62 LOCAL.

7. NOT ACCOMPLISHED.

8. TO HQS COURIER ON 9 DEC 62.

END OF MESSAGE

S E C R E T

Approved For Release 2002/11/14 : CIA-RDP89B00569R000200030061-3

25X1A

Approved For Release 2002/11/14 : CIA-RDP89B00569R000200030061-3